



BRADWELL

CREEK

St
Lawrence
Approach.

Picture taken
near to low
water showing
obstruction in
bend of shallow
creek entrance

No fix on stump of post in middle of creek bend. Only visible at or about low water .

Metal Post position given by GPS Fix taken from a position approximately 15ft North of Hazard

(N51.43.279. – E000.51.481)



Bradwell

Creek

St Lawrence

Approach.

Picture taken near
low water of
obstruction on
shore side of
creek.

Hazards to Navigation

September 2011